

1 Tools Required

Tool	Size
Allen Head Screwdriver	2mm AF
Flat Blade Screwdriver	3mm AF
Pozidriv Screwdrivers	No. 1 for M3 screws No. 2 for M4 screws
Torx Screwdrivers	T10 for M3 screws T20 for M4 screws
Spanners	1/4" AF for D-range locating pins 5.5mm AF for M3 nuts ^a 6mm AF for SMC connector 7mm AF for M4 nuts
Solder	
Soldering Iron	

- a. If you do not have a 5.5mm spanner, you can use long-nosed pliers to carefully grip the M3 nuts on the D-range securing screws and locating pins.

