



**Frequently Asked Questions
27
11 November, 2005**

Model	Question	Solution
TM82xx	Some TM82xx remote head interface boards don't work together.	There has been some development work in this area and unfortunately there is now a degree of incompatibility between some boards. If a remote kit is purchased, then the two boards supplied will be fully compatible. However if boards are for any reason, mixed up with other boards, then a situation could occur where an incompatible "pair" is chosen.

The chart below shows compatibility of TM8200 remote head interface boards.

Boards shown in **red** were early trial boards, and should not be found in the field other than in trial demo radios.

		Control head interface board.		
		220-01721-04	220-01721-02	220-02122-02
Radio interface board.	220-01720-03	√	√	√
	220-02123-01	√	X	√
	226-00606-03	√	√	X
	220-01720-01	√	√	X