



Technical Note TN-1041-SR

Firmware Release T2030 V3.39 Std

26th August 2005

Applicability

This Technical Note applies only to the Tait T2030 Trunked mobile radio.

1. Introduction

Information

The last full release of T2030 firmware was for V3.37 (TN-941-SR). **This firmware has now been replaced by V3.39.**

Detail

The change(s) to the firmware are as follows: -

- Incorrect Operation Of SOS Mode - where it was not possible to have a "Non-Stealth" SOS Mode (refer TIMS45034/ FOCUS19859).

Compatibility

Hardware:

Control board IPN **220-01344-05 to -12** with track modification for CTCSS operation

Control board IPN **220-01344-13 or later.**

No longer supported: T2000-A4500 Plug in CTCSS module is not compatible with current and future firmware versions.

Programming Software:

Trunked Programming Application (TPA) **V2.90** or later (DOS no longer supported).

Compliance Issues

None – unless specifically required by Network operators

CSO Instruction

CSO's – Please inform all logistics, sales and technical staff, and dealers of this release.

2. Issuing Authority

Name and Position of Issuing Officer

Paul Anderson
Customer Support Engineer – T2000

Confidentiality

Confidential – This message or document contains proprietary information intended only for the person(s) or organisation(s) to whom it is addressed. All Recipients are legally obliged to not disclose Tait technological or business information to any persons or organisations without the written permission of Tait.

Distribution Level

Tait and ASC

Document History

Original Release	26 th August 2005	PRA
------------------	------------------------------	-----